
South
North
19,600N
19,800N
20,000N
20,200N
20,400N
surface
overburden
DG-07-280
DG-09-757
DG-07-189
DG-07-203
DG-09-768
DG-08-303
DG-09-765
DG-08-306
DG-09-754
DG-08-373
DG-09-824
6,200m Elev.
6,000m Elev.
5,800m Elev.
5,600m Elev.
CMH
SLDZ
footwall volcanics and sediments
massive flow
pillow flow
0.59/10.0
1.63/7.0
1.09/7.0
1.08/9.0
1.21/11.0
1.58/8.0
1.09/12.0
0.95/28.0
0.80/23.0
1.04/10.0
1.76/34.0
2.49/10.0
1.23/7.5
0.81/32.0
1.27/15.0
1.68/9.0
0.71/26.0
0.63/12.0
1.16/12.0
0.62/14.0
1.13/25.0
0.68/17.0
1.15/19.0
1.79/7.0
0.84/9.0
2.01/7.0
0.93/7.0
2.33/20.0
5.84/11.0
0.76/7.0
1.80/15.0
1.29/19.0
1.01/8.0
1.18/38.0
1.33/12.0
2.62/10.0
1.22/8.0
0.80/10.0
3.41/9.0
1.18/8.0
3.66/12.0
1.63/15.0
1.27/21.0
1.60/60.0
0.97/7.5
1.28/8.0
1.18/7.0
1.41/78.0
3.63/19.0
3.33/41.0
0 50 100 150 200
metres
January 13, 2010
Drill holes (2009) reported on January 13
Current drill holes completed as of January 13
Drill holes previously reported (2007-09)
Drill hole, off-section
Pre-2007 drill hole
Underground workings
Mined stopes
Mineralized intersections
>2.0 g/t Au
0.65 - 2.0 g/t Au
2.11/15.0 g/t Au/metres (capped to 20g/t)
CMH Chert marker horizon
SLDZ Sunday Lake Deformation Zone
Detour Gold Corporation
Detour Lake Property
Ontario
Calcite Zone
Cross Section 18,100E
Looking West